



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS KNOT
Port	MOMA, MOZAMBIQUE
Terminal & Berth No.	MOMA WORKING ANCHORAGE

Port Details

Anchorage approach	ARRIVAL POSITION
Min. depth at anchorage/Channel	14.4M / 642 M
Pilot performance/Tugs condition	N/A
Other information	VESSEL AT ANCHOR

Berth Details

Berth Type	WORKING ANCHORAGE
Minimum depth at Berth/approach/UKC concern	22.0M / 14.4M / 15.65 M
Mooring arrangement	VESSEL AT ANCHOR / 9 SHACKLES IN THE WATER / PORT SIDE ANCHOR/ 3 LINE FORWARD & 2 LINE AFT TO BARGE
Berth Restrictions	N/A
Berth condition/fendering etc	BARGE WITH 2 YOKOHAMA FENDERS
Other information (fendering etc)	

Cargo Operation

Manifold connections	
Terminal courtesy/co-operation	
Safety standard	
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	NO AUTHORITIES ONBOARD
Security (Stowaways/theft threats)	NO TREAT
Spares/Stores/FW supply	N/A
Crew change/Shore leave	N/A
General comments	VESSEL LOADING ILMINETE SAND
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO / 14/02/2020
----------------------	-------------------------------------