



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS OKUDOGO
Port	Nacala. Mozambique
Terminal & Berth No.	Nacala Coal Terminal

**Port Details**

Anchorage approach	Outer Anchorage
Min. depth at anchorage/Channel	22m at anchorage / 19m at channel
Pilot performance/Tugs condition	Satisfactory / Good
Other information	Anchorage area depth is variable (sloping).

**Berth Details**

Berth Type	Concreted Quay
Minimum depth at Berth/approach/UKC concern	19m
Mooring arrangement	4 + 2 Fwd & Aft
Berth Restrictions	NIL
Berth condition/fendering etc	Satisfactory
Other information (fendering etc)	Large fenders. Gangway unable to be landed on quay. Shore extender utilized

**Cargo Operation**

Manifold connections	N/A
Terminal courtesy/co-operation	Satisfactory
Safety standard	Satisfactory / As per port advice
Other information (booster pumps etc)	2 Shore loaders. 5100MT/h max. loading rate

**Additional information**

Authorities(Custom/immig./health)	22 February 2020 upon arrival.
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL
General comments	Safely berthed
Recommendations	

Master's Name / Date

Capt. Brian Coxon / 22 February 2020