

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback

Port Feedback	
Ship Name	IVS Wentworth
Port	Rotterdam, Netherlands
Terminal & Berth No.	Steinweg Berth Waalshaven / Botlek Buoy 66
Port Details	
Anchorage approach	Outer Anchorage Along Maas Approach
Min. depth at anchorage/Channel	Anchorage - 18m
Pilot performance/Tugs condition	Good / Satisfactory
Other information	
Berth Details	
Berth Type	Sheltered
Minimum depth at Berth/approach/UKC concern	Approach = 18m / Berth = 13.8m
Mooring arrangement	4 + 2 (F&A)
Berth Restrictions	Vessel to berth on Rising Tide
Berth condition/fendering etc	Good, Clean and Saftisfactory Condition with +- 20m bollard distance.
Other information (fendering etc)	Element Vertical Wooden Fenders in excellent condition.
Cargo Operation	
Manifold connections	-
Terminal courtsey/co-operation	Satisfactory
Safety standard	High Safety Standard
Other information (booster pumps etc)	-
Additional information	
Authorities(Custom/immig./health)	Due to Covid-19 Pandemic, Agent handled all documentation.
Security (Stowaways/theft threats)	ISPS Port Compliant, Port is access controlled.
Spares/Stores/FW supply	Allowed, Stores & FW Supplied.
Crew change/Shore leave	Crew Change successfully carried out 5 Off 2 On / Shore Leave granted but Master denied shore leave due to COVID-19 Pandemic
General comments	granted but Master denied shore leave due to COVID-19 Pandemic Port of Rotterdam well maintained with very clean and organised

 General comments
 I on on reaction and organized

 Recommendations

Master's Name / Date Capt. Kenneth A. Brown / 12 Sep 2020