



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	Sluiskil Netherlands
Terminal & Berth No.	Yara Terminal

Port Details

Anchorage approach	Vessel pick up pilot upon arrival p/stn via Steenbank from SB Anchorage
Min. depth at anchorage/Channel	Channel depth 13.5m
Pilot performance/Tugs condition	Pilot performance Good / Tugs Good
Other information	Pilot board at Steenbank pilot boarding area by pilot boat

Berth Details

Berth Type	Private berth Yara Terminal
Minimum depth at Berth/approach/UKC concern	11.5
Mooring arrangement	4 + 2 arrangement fwd & aft
Berth Restrictions	no restriction
Berth condition/fendering etc	Good
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	Loading Ammonium Nitrate

Additional information

Authorities(Custom/immig./health)	Authorities onboard after ships alongside
Security (Stowaways/theft threats)	No stowaway threats in this port
Spares/Stores/FW supply	No supply
Crew change/Shore leave	1 onsigner and 1 offsigner
General comments	
Recommendations	

Master's Name / Date

Capt Marek Edward Liedtke