

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

## Port Feedback

FUILFEEUDACK	
Ship Name	IVS RAFFLES
Port	GISBORNE NEW ZEALAND
Terminal & Berth No.	BERTH 7
Port Details	
Anchorage approach	
Min. depth at anchorage/Channel	
Pilot performance/Tugs condition	GOOD, TUGS HAVE ENOUGH HP
Other information	
Berth Details	
Berth Type	GENERAL CARGO BERTH
Minimum depth at Berth/approach/UKC concern	
Mooring arrangement	NORMAL 4+2
Berth Restrictions	NO RESTRICTIONS, NO WALKING ALLOWED
Berth condition/fendering etc	GOOD
Other information (fendering etc)	
Cargo Operation	
Manifold connections	NO MANIFOLD CONNECTIONS
Terminal courtsey/co-operation	GOOD
Safety standard	HIGH

Safety standard	HIGH
Other information (booster pumps etc)	
Additional information	
Authorities(Custom/immig./health)	GOOD
Security (Stowaways/theft threats)	SECURITY ON MAIN GATE
Spares/Stores/FW supply	SMALL PORT/STORING UNAVAILABLE
Crew change/Shore leave	CREW CHANGE POSSIBLE / SL IS ALLOWED
General comments	
Recommendations	
Master's Name / Date	