

Recommendations

Master's Name / Date

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

| IVS RAFFLES                               |
|---|
| TAURANGA, NEW ZEALAND                     |
| SOUTH BERTH                               |
|   |
| NO TRAFFIC, WIDE AREA                     |
|   |
| ALL GOOD                                  |
| MOUNTAIN SERVES AS BREAKWATER             |
|   |
| GENERAL CARGO BERTH MOSTLY LOGS           |
|   |
|   |
| NO RESTRICTIONS,EXCEPT NO WALKING ALLOWED |
| GOOD BERTH, WOODEN FENDERS                |
|   |
|   |
|   |
| GOOD                                      |
| SAFETY IS HIGH                            |
|   |
|   |
| GOOD                                      |
| SECURITY AVAILABLE ON MAIN GATE           |
| GOOD SPARES AND STORES AVAILABLE          |
| CREW CHANGE POSSIBLE, SL IS ALLOWED       |
| GOOD PORT                                 |
|   |
|   |