

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

REPORTING FORMS MANUAL

Port Feedback

Master's Name / Date

Port Feedback	
Ship Name	IVS PHINDA
Port	TAURANGA-2
Terminal & Berth No.	BERTH NO 9
Port Details	
Anchorage approach	
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	N/A
Other information	GOOD
Berth Details	
Berth Type	STBD SIDE
Minimum depth at Berth/approach/UKC concern	
Mooring arrangement	fwd (4 Head / 2 Spring) / Aft (4 Head / 2 Spring)
Berth Restrictions	None
Berth condition/fendering etc	Good
Other information (fendering etc)	Good
Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	4 SHIPS CRANE
Additional information	
Authorities(Custom/immig./health)	
Security (Stowaways/theft threats)	Security Level 1
Spares/Stores/FW supply	
Crew change/Shore leave	No Crew Change / Yes
General comments	
Decemberdations	
Recommendations	

Capt. George S. Sarmiento