



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS KNOT
Port	CRISTOBAL, PANAMA
Terminal & Berth No.	INNER ANCHORAGE

Port Details

Anchorage approach	PRECAUTIONARY AREA
Min. depth at anchorage/Channel	17.80M / 17.94M
Pilot performance/Tugs condition	GOOD PILOT PERFORMANCE
Other information	

Berth Details

Berth Type	ANCHORAGE AREA
Minimum depth at Berth/approach/UKC concern	12.50M / 12.62M / 1.89M
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	AGENT ONBOARD/ PANAMA CANAL INSPECTOR ONBOARD
Security (Stowaways/theft threats)	NO TREATS
Spares/Stores/FW supply	SUPPLIED PROVISION
Crew change/Shore leave	N/A
General comments	VESSEL TAKING BUNKER
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO / 07/11/2019
----------------------	-------------------------------------