



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS KNOT
Port	PUNTA RINCON, PANAMA
Terminal & Berth No.	TERMINAL 2

Port Details

Anchorage approach	SEA BUOY
Min. depth at anchorage/Channel	37.32M/ 48.30M
Pilot performance/Tugs condition	GOOD PILOT PERFORMANCE/ GOOD CONDITION OF TUGS
Other information	2 TUGS ASSIST PER SHIFTING

Berth Details

Berth Type	STANDARD BERTH
Minimum depth at Berth/approach/UKC concern	18.20M / 18.50M / 7.64M
Mooring arrangement	8 LINES FORWARD/ 8 LINES AFT
Berth Restrictions	NO DRAFT RESTRICTION
Berth condition/fendering etc	SBM TYPE OF MOORING
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	AGENT ONBOARD AND SURVEYOR ONBOARD
Security (Stowaways/theft threats)	NO TREATS
Spares/Stores/FW supply	NOT AVAILABLE
Crew change/Shore leave	NOT AVAILABLE
General comments	
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO / 03/11/2019
----------------------	-------------------------------------