



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	MATARANI, PERU
Terminal & Berth No.	BERTH A

Port Details

Anchorage approach	SMALL AREA
Min. depth at anchorage/Channel	DEEP WATER ANCHORAGE IF ANCHORAGE FULL
Pilot performance/Tugs condition	GOOD/GOOD
Other information	

Berth Details

Berth Type	OPEN BERTH,LARGE SWELL AT TIMES,NOT SHELTERED
Minimum depth at Berth/approach/UKC concern	SUFFICIENT/AT LARGE ANGLE/NONE
Mooring arrangement	4+2+2, MOORING BOATS USED
Berth Restrictions	NO SHORE LEAVE
Berth condition/fendering etc	GOOD CONDITION
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	SATISFACTORY
Safety standard	SATISFACTORY
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	VISTED AT ANCHORAGE PRIOR BERTHING
Security (Stowaways/theft threats)	LVL1
Spares/Stores/FW supply	STORES AT ANCHORAGE,
Crew change/Shore leave	POSSIBLE,WITH PRIOR ARRANGEMENTS FOR BOAT
General comments	
Recommendations	

Master's Name / Date

BUDNY DANIEL/15.11.2020



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	CALLAO,PERU
Terminal & Berth No.	BERTH NO 4

Port Details

Anchorage approach	N/A
Min. depth at anchorage/Channel	N/A / 23MTRS
Pilot performance/Tugs condition	GOOD/GOOD
Other information	

Berth Details

Berth Type	GENERAL CARGO
Minimum depth at Berth/approach/UKC concern	
Mooring arrangement	4+2+2 FWD & AFT
Berth Restrictions	LENGTH TO FIT HANDY MAX VESSELS
Berth condition/fendering etc	GOOD/GOOD
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	GOOD/GOOD
Safety standard	AVERAGE
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	CUSTOMS/AGENT/HEALTH/IMMIGRATION
Security (Stowaways/theft threats)	SECURITY LEVEL 1/NO THREATS
Spares/Stores/FW supply	STORES/PROVISIONS SUPPLIED
Crew change/Shore leave	YES AVAILABLE/YES
General comments	SECURITY IS VERY HIGH AT MAIN GATES,CREW TO BE ESCORTED ASHORE WITH AGENT
Recommendations	

Master's Name / Date

CAPT BUDNY DANIEL/2019.11.01



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	MISSISSIPPI, RIVER
Terminal & Berth No.	DESTREHAN BERTH

Port Details

Anchorage approach	N/A
Min. depth at anchorage/Channel	27MTRS
Pilot performance/Tugs condition	GOOD/GOOD
Other information	

Berth Details

Berth Type	BERTH & MOORING BUOYS
Minimum depth at Berth/approach/UKC concern	16/(N/A)/NONE
Mooring arrangement	4+2+2 (FWD & AFT)
Berth Restrictions	LENGTH FOR HANDYMAX SIZE VESSELS
Berth condition/fendering etc	BELOW AVERAGE/FENDERING POOR CONDITION
Other information (fendering etc)	CERTAIN FENDERS DAMAGED AND MOORING BUOYS SITUATED LONG DISTANCE FROM VESSEL.

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	GOOD/GOOD
Safety standard	AVERAGE
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	CUSTOMS/AGENT/HEALTH/IMMIGRATION
Security (Stowaways/theft threats)	SECURITY LEVEL 1/NO THREATS
Spares/Stores/FW supply	FRESH WATER SUPPLIED
Crew change/Shore leave	YES/YES
General comments	GANGWAY TO BE CHECKED REGULARLY DUE TO CRANE OPERATING CLOSELY, PORTABLE GANGWAY TO BE USED DUE TO HEIGHT OF QUAY AND CRANE MOVEMENTS
Recommendations	

Master's Name / Date

CAPT BUDNY DANIEL/ 2019.10.16



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	MISSISSIPPI RIVER,
Terminal & Berth No.	YARA BERTH

Port Details

Anchorage approach	N/A
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	GOOD/GOOD
Other information	WITHIN MISSISSIPPI RIVER

Berth Details

Berth Type	GENERAL CARGO, DISCHARGE INTO HOPPERS
Minimum depth at Berth/approach/UKC concern	16.0M/N/A/NONE
Mooring arrangement	4+2 FWD AFT
Berth Restrictions	NIL
Berth condition/fendering etc	GOOD/ADEQUATE
Other information (fendering etc)	N/A

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	SATISFACTORY
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	CUSTOMS/AGENT/HEALTH/IMMIGRATION
Security (Stowaways/theft threats)	SECURITY LEVEL 1/NO THREATS
Spares/Stores/FW supply	SPARES & STORES
Crew change/Shore leave	NO/YES
General comments	GANGWAY TO BE CHECKED REGULARLY DUE TO CRANE OPERATING CLOSELY
Recommendations	

Master's Name / Date

CAPT BUDNY DANIEL/2019.10.04



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	SLUISKIL
Terminal & Berth No.	NUMBER 02

Port Details

Anchorage approach	NO
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	GOOD/GOOD
Other information	

Berth Details

Berth Type	GENERAL CARGO, DISCHARGE INTO BARGES ALONGSIDE
Minimum depth at Berth/approach/UKC concern	14.4m
Mooring arrangement	4 + 2 FWD & AFT
Berth Restrictions	NIL
Berth condition/fendering etc	GOOD
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	CUSTOMS/AGENT/HEALTH/IMMIGRATION
Security (Stowaways/theft threats)	SECURITY LEVEL 1/NO THREATS
Spares/Stores/FW supply	SPARES & STORES/BUNKERS RECEIVED
Crew change/Shore leave	YES
General comments	NIL
Recommendations	

Master's Name / Date	Capt BUDNY DANIEL/ 25-08-2019
----------------------	-------------------------------