



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	CEBU
Terminal & Berth No.	CEBU INTERNATIONAL PORT BERTH 5-6

Port Details

Anchorage approach	OUTER ANCHOR BERTH SOUTH APPROACH
Min. depth at anchorage/Channel	20m / 9m
Pilot performance/Tugs condition	SATISFACTORY / GOOD CONDITION
Other information	

Berth Details

Berth Type	CONCRETE / FENDERED
Minimum depth at Berth/approach/UKC concern	8m / 9m / NIL
Mooring arrangement	3 + 2 FWD & AFT
Berth Restrictions	NIL
Berth condition/fendering etc	GOOD / SATISFACTORY
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	GOOD / SATISFACTORY
Safety standard	SATISFACTORY
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	CUSTOM / IMMIGRATION CLEARED AT BERTH
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	STORES / PROVISIONS DELIVERED / FW SUPPLY 50 MT
Crew change/Shore leave	NIL / NIL DUE TO COVID-19 PRECAUTIONS
General comments	VESSEL WILL DISCHARGE SALT IN BULK - 12,100 MT ESTIMATED OPERATION TIME WILL BE 3 DAYS
Recommendations	

Master's Name / Date	ADAM BORNA / 15-03-2020
----------------------	-------------------------