



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	MANILA, PHILIPPINES
Terminal & Berth No.	NIL

Port Details

Anchorage approach	MANILA BAY ANCHORAGE
Min. depth at anchorage/Channel	14.3 m
Pilot performance/Tugs condition	NIL
Other information	

Berth Details

Berth Type	NIL
Minimum depth at Berth/approach/UKC concern	20m / 14.3 m
Mooring arrangement	NIL
Berth Restrictions	COVID-19 PRECAUTIONS
Berth condition/fendering etc	NIL
Other information (fendering etc)	

Cargo Operation

Manifold connections	NIL
Terminal courtesy/co-operation	NIL
Safety standard	NIL
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	AUTHORITIES CLEARED AT ANCHORAGE
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES / NIL DUE TO COVID-19 PRECAUTIONS
General comments	
Recommendations	

Master's Name / Date

JAMES VIC LEGASON 09-10-2020