



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS NORTH BERWICK
Port	MANILA, PHILIPPINES
Terminal & Berth No.	QUARANTINE ANCHORAGE

Port Details

Anchorage approach	Approached from the SW
Min. depth at anchorage/Channel	16m / 20m
Pilot performance/Tugs condition	na / nil
Other information	

Berth Details

Berth Type	Anchorage Area
Minimum depth at Berth/approach/UKC concern	16m / 20m / nil sufficient ukc
Mooring arrangement	Starbord anchor 5 shackles in the water
Berth Restrictions	nil
Berth condition/fendering etc	Sand Bottom, Good holding ground
Other information (fendering etc)	

Cargo Operation

Manifold connections	NA
Terminal courtesy/co-operation	NA
Safety standard	NA
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	Fair
Security (Stowaways/theft threats)	Appears vulnerable but no issues experienced. Did not use guards.
Spares/Stores/FW supply	NA
Crew change/Shore leave	Crew change completed
General comments	
Recommendations	

Master's Name / Date

Capt. Mike Melly / 26 SEP 2020