



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS OKUDOGO
Port	Poro Point, San Fernando, La Union, Philippines
Terminal & Berth No.	Outer Anchorage

Port Details

Anchorage approach	Outer Anchorage. Near Pilot station.
Min. depth at anchorage/Channel	38m
Pilot performance/Tugs condition	N/A
Other information	Anchorage area provides good holding ground

Berth Details

Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	15 Aug. 2020 upon arrival
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	N/A
Crew change/Shore leave	15 Aug. 2020 upon arrival
General comments	Safely berthed
	Care should be taken in the approaches due to the formation of reefs and many wrecks. Foul ground and shoals extend NE towards the entrance from the E side of the peninsular which extends S from San Fernando Point.
Recommendations	Depths of less than 5.5m front W shore and extend up to 3 cables, between San Fernando and E entrance point.
Master's Name / Date	CAPT. PIOTR MACIEJ MONTWILL / 15 AUG. 2020