

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback	
Ship Name	IVS THANDA
Port	MESAIEED, QATAR
Terminal & Berth No.	QAFCO BERTH 3
Port Details	
Anchorage approach	INNER ANCHORAGE C3
Min. depth at anchorage/Channel	11.3m / 13.5m
Pilot performance/Tugs condition	SATISFACTORY / GOOD CONDITION
Other information	
Berth Details	
Berth Type	CONCRETE / FENDERED
Minimum depth at Berth/approach/UKC concern	12.5m / 12.5m / NIL
Mooring arrangement	3 + 2 + 2 FWD & AFT
Berth Restrictions	COVID-19 PRECAUTIONS
Berth condition/fendering etc	GOOD / SATISFACTORY
Other information (fendering etc)	
Cargo Operation	-
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD / SATISFACTORY
Safety standard	SATISFACTORY
Other information (booster pumps etc)	N/A
Additional information	
Authorities(Custom/immig./health)	CUSTOMS CLEARED AT BERTH
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL / NIL DUE TO COVID-19 PRECAUTIONS
General comments	VESSEL WILL LOAD GRANULAR UREA - 32,889 MT / ESTIMATED OPERATION TIME WILL BE 4 DAYS
Recommendations	

Master's Name / Date ADAM BORNA / 16-06-2020