

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

_		_	_	_	_
Pο	-4	$\mathbf{E}_{\sim}$		h-	~  -
-()				111	IL:K

Ship Name	IVS OKUDOGO	
Port	Port East, La Reunion	
Terminal & Berth No.	Multi-Purpose Terminal / Berth no.21	
Port Details		
A b b	NE of the part, in Paio de la Responsion	

Port Details	
Anchorage approach	NE of the port, in Baie de la Possession
Min. depth at anchorage/Channel	20.0m / 16.0m
Pilot performance/Tugs condition	SATISFACTORY
	Entry into Est Port is from 0400-2200hrs. Night entry is between
Other information	1800 and 0600hrs.

Berth Details	
Berth Type	MULTI PURPOSE BERTH / Liquid, solid bulk
Minimum depth at Berth/approach/UKC concern	12.7m/16.0m/3.0m
Mooring arrangement	4-2 FWD and AFT
Berth Restrictions	NIL
Berth condition/fendering etc	Satisfactory / Rubber
Other information (fendering etc)	Satisfactory / Rubber

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Satisfactory
Safety standard	Satisfactory / As per port advice
Other information (booster pumps etc)	N/A

Additional information	
Authorities(Custom/immig./health)	01 OCT. 2020 / On arrival Berth
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	Crew change are allowed / Shoreleave not allowed.
General comments	SAFELY BERTHED
	ALWAYS SECURE RAT GUARDS AND SHOULD BE VIGILANT IN PORT
Recommendations	WATCH.

Master's Name / Date	CAPT. PIOTR MACIEJ MONTWILL / 04 OCT. 2020