



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS GLENEAGLES
Port	PORT REUNION, REUNION ISLAND
Terminal & Berth No.	BERTH NO. 20

Port Details

Anchorage approach	VSL DRIFTING 10 NM OFF PORT REUNION / NO ANCHORAGE
Min. depth at anchorage/Channel	15.0 M
Pilot performance/Tugs condition	GOOD AND SATISFACTORY
Other information	ALL IN GOOD ORDER

Berth Details

Berth Type	BULK CARRIER BERTH
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	(4 + 2) FORWARD AND AFT
Berth Restrictions	NIL
Berth condition/fendering etc	ALL GOOD
Other information (fendering etc)	N/A

Cargo Operation

Manifold connections	VIA SHIP'S CRANE AND SHIP'S GRAB
Terminal courtesy/co-operation	ALL GOOD
Safety standard	ALL GOOD
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	ALL GOOD
Security (Stowaways/theft threats)	ALL GOOD
Spares/Stores/FW supply	ALL GOOD
Crew change/Shore leave	NIL / ALL GOOD
General comments	ALL GOOD
Recommendations	

Master's Name / Date	CAPT. DENIS R. DIEGO
----------------------	----------------------