



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

| | |
|----------------------|------------------------|
| Ship Name | IVS HIRONO |
| Port | JUBAIL INDUSTRIAL PORT |
| Terminal & Berth No. | BERTH 21 |

Port Details

| | |
|----------------------------------|--|
| Anchorage approach | Designated anchorage west and south west of fairway buoy |
| Min. depth at anchorage/Channel | 16m |
| Pilot performance/Tugs condition | Pilot is very professional / Tugs good condition |
| Other information | |

Berth Details

| | |
|---|--|
| Berth Type | CONCRETE |
| Minimum depth at Berth/approach/UKC concern | 14m |
| Mooring arrangement | FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines |
| Berth Restrictions | Nil |
| Berth condition/fendering etc | well maintained berth / good fender |
| Other information (fendering etc) | arch fender |

Cargo Operation

| | |
|---------------------------------------|------------------|
| Manifold connections | N/A |
| Terminal courtesy/co-operation | Good cooperation |
| Safety standard | Normal |
| Other information (booster pumps etc) | |

Additional information

| | |
|------------------------------------|-----------------------------------|
| Authorities(Custom/immig./health) | Normal port formalities |
| Security (Stowaways/theft threats) | Shore watchman |
| Spares/Stores/FW supply | Available |
| Crew change/Shore leave | na |
| General comments | Vessel berthed portside alongside |
| | |
| Recommendations | |

Master's Name / Date

R.BARTOSIAK / 03 NOV 2018