



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS HIRONO
Port	PORT VICTORIA, SEYCHELLES
Terminal & Berth No.	ANCHORAGE BET NO. 9 & 11

Port Details	
Anchorage approach	FROM THE NORTH
Min. depth at anchorage/Channel	16.3
Pilot performance/Tugs condition	N/A
Other information	ANCHORAGE ONLY TO DROP ARMED GUARDS

Berth Details	
Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	N/A

Cargo Operation	
Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	N/A

Additional information	
Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	SECURITY LVL 1
Spares/Stores/FW supply	YES
Crew change/Shore leave	Possible
General comments	ANCHORED AT ANCHORAGE NO. 3
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO/26 MARCH 2019
----------------------	--------------------------------------