



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS NORTH BERWICK
Port	SINGAPORE
Terminal & Berth No.	Anchorage Eastern Bunkering Charlie

**Port Details**

Anchorage approach	From PEBG C in E heading WNW
Min. depth at anchorage/Channel	30m / 40m
Pilot performance/Tugs condition	Good / No tugs used
Other information	

**Berth Details**

Berth Type	Bunkering Anchorage Area
Minimum depth at Berth/approach/UKC concern	30m / 40m
Mooring arrangement	Stbd anchor used 6 shackles in the water
Berth Restrictions	none
Berth condition/fendering etc	Good holding ground
Other information (fendering etc)	Congested

**Cargo Operation**

Manifold connections	Good
Terminal courtesy/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	

**Additional information**

Authorities(Custom/immig./health)	Good / Done digitally
Security (Stowaways/theft threats)	Good
Spares/Stores/FW supply	Available
Crew change/Shore leave	Crew changes possible but involves excessive paperwork
General comments	
Recommendations	

Master's Name / Date

Capt. Mike Melly / 12 Sep 2020