

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	IVS OKUDOGO	
Port	Singapore	
Terminal & Berth No.	Eastern Bunkering Bravo Anchorage	
Port Details		
	E DEDOO 1 1 1 1 1	

Port Details	
Anchorage approach	From PEBGC approach via fairway
Min. depth at anchorage/Channel	32m
Pilot performance/Tugs condition	Satisfactory
Other information	Anchorage area congested

Berth Details	
Berth Type	Anchorage Area
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	N/A

Cargo Operation		
Manifold connections	N/A	
Terminal courtsey/co-operation	N/A	
Safety standard	N/A	
Other information (booster pumps etc)	N/A	

Additional information	
Authorities(Custom/immig./health)	e-Pans / No boarding required
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	Quarterly Stores, Spares and Bunkers
Crew change/Shore leave	NIL
General comments	Safely Anchored
Recommendations	

Master's Name / Date	Capt. Brian Coxon / 14 October 2019