

Port Feedback

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Rev : App I

Ship Name	IVS Swinley Forest
Port	Singapore
Terminal & Berth No.	Eastern Bunkering Bravo Anchorage
Port Details	
Anchorage approach	From PEBGC approach via fairway
Min. depth at anchorage/Channel	32m
Pilot performance/Tugs condition	Satisfactory
Other information	Anchorage area congested
Berth Details	
Berth Type	Anchorage Area
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	N/A
Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	N/A
Additional information	
Authorities(Custom/immig./health)	e-Pans / No boarding required
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	Quarterly Stores, Spares and Bunkers
Crew change/Shore leave	1 Off (Engine Cadet)
General comments	Safely Anchored
Recommendations	

Master's Name / Date

Capt. Miroslaw Boguslaw Kaczmarczyk / 02 November 2020