



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	SINGAPORE, SINGAPORE
Terminal & Berth No.	ESP ANCHORAGE

**Port Details**

Anchorage approach	EASTERN SPECIAL PURPOSE ANCHORAGE
Min. depth at anchorage/Channel	21.1m
Pilot performance/Tugs condition	SATISFACTORY / NIL
Other information	

**Berth Details**

Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	21.1m
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	

**Cargo Operation**

Manifold connections	STARBOARD SIDE BUNKER CONNECTION
Terminal courtesy/co-operation	VTIS CENTRAL
Safety standard	SATISFACTORY
Other information (booster pumps etc)	

**Additional information**

Authorities(Custom/immig./health)	N/A
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	YES/YES
Crew change/Shore leave	NIL / NIL DUE TO COVID-19 PRECAUTIONS
General comments	VSL RECEIVED BUNKER ,STORE, AND PROVISION INORDER TO CONTINUE THE VOYAGE TO KHALIFA
Recommendations	

Master's Name / Date

JAMES VIC LEGASON 15-10-2020