

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS WENTWORTH
Port	SINGAPORE
Terminal & Berth No.	ALL PURPOSE ANCHORAGE "A"

Port Details	
Anchorage approach	Call Singapore pilot VHF ch 20 2 hours before arrival
Min. depth at anchorage/Channel	34.0M
Pilot performance/Tugs condition	Pilot good, no tugs
Other information	

Berth Details	
Berth Type	NIL
Minimum depth at Berth/approach/UKC concern	34.0M
Mooring arrangement	NIL
Berth Restrictions	NIL
Berth condition/fendering etc	NIL
Other information (fendering etc)	NIL

Cargo Operation	
Manifold connections	Good
Terminal courtsey/co-operation	satisfactory
Safety standard	satisfactory
Other information (booster pumps etc)	NIL

Additional information		
Authorities(Custom/immig./health)	satisfactory	
Security (Stowaways/theft threats)	ISPS Port compliant	
Spares/Stores/FW supply	Stores, Provision and Bunker received	
Crew change/Shore leave	Shore leave not permitted	
General comments		
Recommendations		

Master's Name / Date	POMORSKI PIOTR P.