



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

| | |
|----------------------|-------------------------------|
| Ship Name | IVS WENTWORTH |
| Port | SINGAPORE |
| Terminal & Berth No. | SINGAPORE EASTERN ANCHORAGE B |

Port Details

| | |
|----------------------------------|----------------------------------|
| Anchorage approach | Singapore Eastern Anchorage B |
| Min. depth at anchorage/Channel | 32.83m |
| Pilot performance/Tugs condition | 1 PILOT / NO TUGS USED |
| Other information | Singapore Port Control VHF Ch 09 |

Berth Details

| | |
|---|-----------|
| Berth Type | Anchorage |
| Minimum depth at Berth/approach/UKC concern | 19.03m |
| Mooring arrangement | NIL |
| Berth Restrictions | NIL |
| Berth condition/fendering etc | NIL |
| Other information (fendering etc) | NIL |

Cargo Operation

| | |
|---------------------------------------|-----|
| Manifold connections | NIL |
| Terminal courtesy/co-operation | NIL |
| Safety standard | NIL |
| Other information (booster pumps etc) | NIL |

Additional information

| | |
|------------------------------------|---|
| Authorities(Custom/immig./health) | Satisfactory |
| Security (Stowaways/theft threats) | Additional Security Watches on Deck |
| Spares/Stores/FW supply | Received provisions, bunkers and spares |
| Crew change/Shore leave | Nil |
| General comments | |
| | |
| Recommendations | |

Master's Name / Date

Capt. Krzysztof Z. Senczuk