



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS HIRONO
Port	CAPE TOWN
Terminal & Berth No.	BERTH B

Port Details	
Anchorage approach	East of Pilot Boarding Ground
Min. depth at anchorage/Channel	15.9
Pilot performance/Tugs condition	Good / Fair
Other information	

Berth Details	
Berth Type	Concrete
Minimum depth at Berth/approach/UKC concern	11.9
Mooring arrangement	4 x 2
Berth Restrictions	None
Berth condition/fendering etc	Good
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD
Safety standard	FAIR
Other information (booster pumps etc)	Discharging Ops Via Ships Crane and Shore Grab by trucks.

Additional information	
Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	Indemic. Port Security was deployed and Dog Search prior departure.
Spares/Stores/FW supply	Possible
Crew change/Shore leave	Possible / Shorepass needed
General comments	Good
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO / 16 MAY 2019
----------------------	--------------------------------------