



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	MV IVS NORTH BERWICK
Port	DURBAN, SOUTH AFRICA
Terminal & Berth No.	BULK CONNECTION NO. 4

Port Details

Anchorage approach	YES. NE of racon buoy
Min. depth at anchorage/Channel	53m in the anchorage
Pilot performance/Tugs condition	Good performance / 2 tugs, good condition
Other information	Nil

Berth Details

Berth Type	Coal Berth
Minimum depth at Berth/approach/UKC concern	10.6m / Tidal Sailing
Mooring arrangement	Port side alongside 4 + 2 fwd and aft
Berth Restrictions	10.6m
Berth condition/fendering etc	Good
Other information (fendering etc)	Nil

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	Good (stowaway & theft threat)
Spares/Stores/FW supply	Available
Crew change/Shore leave	No shore leave / Limited crew change possible
General comments	Berth is good and receiving stores & provision from berth.
Recommendations	NIL

Master's Name / Date

Capt. GODFREY G. GIMOTEA / 21 AUG 2020