



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS WENTWORTH
Port	Durban, South Africa
Terminal & Berth No.	Island View Berth 3

Port Details

Anchorage approach	Vessels are permitted to anchor in outer anchorage, 4nm E of Durban breakwater.
Min. depth at anchorage/Channel	The outer channel, commencing 4nm from the breakwater, has a dredged depth of 19.0m and an average width of 222m, with a depth of 16.0m in the harbour basin.
Pilot performance/Tugs condition	Satisfactory/ 2 Tugs used.
Other information	

Berth Details

Berth Type	Sheltered Berth
Minimum depth at Berth/approach/UKC concern	Depth at berth 12.8m
Mooring arrangement	Forward and Aft (4+2)
Berth Restrictions	NIL
Berth condition/fendering etc	Berth is in good condition as well as fenders.
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Satisfactory
Safety standard	High Safety standard
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	Satisfactory
Security (Stowaways/theft threats)	ISPS Port Compliant/ Provided with 3 Security Personnel each shift for stow away watch
Spares/Stores/FW supply	Provisions,Stores,Spares received
Crew change/Shore leave	No Crew change/Shore Leave due to COVID-19 Pandemic
General comments	
Recommendations	

Master's Name / Date	Capt. Benjamin M. Estolas / 27 Mar 2020
----------------------	---