

Master's Name / Date

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By: BMM

## REPORTING FORMS MANUAL

Port Feedback	

Port Feedback		
Ship Name	IVS BOSCH HOEK	
Port	DURBAN SOUTH AFRICA	
Terminal & Berth No.	OPL ANCHORAGE ONLY (PROVISION AND SHIPS STORES)	
Port Details		
Anchorage approach	OPL ANCHORAGE	
Min. depth at anchorage/Channel	55.8M	
Pilot performance/Tugs condition	N/A	
Other information	N/A	
Berth Details		
Berth Type	N/A	
Minimum depth at Berth/approach/UKC concern	N/A	
Mooring arrangement	STARBOARD ANCHOR / 6 SHACKLE ON THE WATER	
Berth Restrictions	N/A	
Berth condition/fendering etc	N/A	
Other information (fendering etc)	N/A	
Cargo Operation		
Manifold connections	N/A	
Terminal courtsey/co-operation	N/A	
Safety standard	AS PER PORT ADVICED	
Other information (booster pumps etc)	N/A	
Additional information		
Authorities(Custom/immig./health)	06.NOV 2019 / AT OPL ANCHORAGE	
Security (Stowaways/theft threats)	NIL / ISPS STRICTLY IMPLEMENTED	
Spares/Stores/FW supply	06-NOV.2019/RECEIVED PROVISIONS/SHIPS STORES	
Crew change/Shore leave	NIL	
General comments	SAFELY ANCHORED	
December detical	ALWAYS DE VICH ANT IN ANCHOR WATCH MONITOR SHIP POSITION	
Recommendations	ALWAYS BE VIGILANT IN ANCHOR WATCH, MONITOR SHIP POSITION REGULARLY. MONITOR INFORMATION FROM VTS.	

CAPT. MIROSLAW B. KACZMARCZYK / 05 NOV. 2019