

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback

Port Feedback	
Ship Name	IVS GLENEAGLES
Port	PORT ELIZABETH, SOUTH AFRICA
Terminal & Berth No.	BERTH NO. 103
Port Details	
Anchorage approach	ANCHORAGE NO. 1
Min. depth at anchorage/Channel	14.32 M
Pilot performance/Tugs condition	GOOD AND SATISFACTORY
Other information	ALL IN GOOD ORDER
Berth Details	
Berth Type	BULK CARRIER BERTH
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	(4 + 2) FORWARD AND AFT
Berth Restrictions	NIL
Berth condition/fendering etc	ALL GOOD
Other information (fendering etc)	N/A
Cargo Operation	
Manifold connections	VIA SHORE SKIPS
Terminal courtsey/co-operation	ALL GOOD
Safety standard	ALL GOOD
Other information (booster pumps etc)	NIL
Additional information	
Authorities(Custom/immig./health)	ALL GOOD
Security (Stowaways/theft threats)	ALL GOOD
Spares/Stores/FW supply	ALL GOOD
Crew change/Shore leave	ALL WITHIN SCHEDULE WITHOUT DELAY / ALL GOOD
General comments	ALL GOOD
Recommendations	
Master's Name / Date	CAPT. DENIS R. DIEGO
· · · · · · · · · · · · · · · · · · ·	