



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS HIRONO
Port	RICHARDS BAY, S.A
Terminal & Berth No.	BERTH 708

Port Details	
Anchorage approach	Anchorage is located SW of Pilot Station
Min. depth at anchorage/Channel	19.5
Pilot performance/Tugs condition	Good / Good
Other information	

Berth Details	
Berth Type	Concrete
Minimum depth at Berth/approach/UKC concern	18.9m/No restriction
Mooring arrangement	4X2 (4 - HEAD LINES / 2 - SPRING LINES)
Berth Restrictions	18.9m/No restriction
Berth condition/fendering etc	GOOD
Other information (fendering etc)	STBD SIDE ALONGSIDE

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD
Safety standard	SATISFACTORY
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	LIMITED DUE TO COVID RESTRICTION
Security (Stowaways/theft threats)	YES. PORT SECURITY IS HIRED. DOG SEARCH ON DEPARTURE
Spares/Stores/FW supply	AVAILABLE
Crew change/Shore leave	BSN, AB, OS, OLR & WIPER
General comments	PORT FACILITY SECURITY IN LEVEL 2 AND SHIPS SECURITY LEVEL AS WELL
	MONITOR DE-BALLASTING OPERATIONS DUE TO VERY
Recommendations	

Master's Name / Date	CAPT. ARTHUR D. BATA 17 OCT 2020
----------------------	----------------------------------