



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS GLENEAGLES
Port	LAS PALMAS, SPAIN
Terminal & Berth No.	ANCHORAGE

Port Details

Anchorage approach	Good anchorage in the roads sheltered against NE/N/NW winds in the S Anchorage and against N/NW winds at the N Anchorage. Both have a sand bottom and are under the surveillance of Las Palmas Port Control radar.
Min. depth at anchorage/Channel	33.0m charted depth during anchorage
Pilot performance/Tugs condition	N/A
Other information	ESLPA / Ø 28-06N \wedge 015-24E / Stbd Anchor used

Berth Details

Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	Nil

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	Nil
Security (Stowaways/theft threats)	ISPS compliant / MARSEC Level 1
Spares/Stores/FW supply	Available via Agent & Ship's Chandler
Crew change/Shore leave	Yes
General comments	Vsl at anchor for Bunkering operation
Recommendations	Maintain safety & security watch at all times

Master's Name / Date	CAPT. DENIS DIEGO / 27 FEB 2020
----------------------	---------------------------------