

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS GLENEAGLES
Port	DAR ES SALAAM, TANZANIA
Terminal & Berth No.	BERTH NO. 3

Port Details	14.5 M
Anchorage approach	ALL GOOD
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	GOOD AND SATISFACTORY
Other information	ALL IN GOOD ORDER

Berth Details	
Berth Type	BULK CARRIER BERTH
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	(4 + 2) FORWARD AND AFT
Berth Restrictions	NIL
Berth condition/fendering etc	ALL GOOD
Other information (fendering etc)	N/A

Cargo Operation	
Manifold connections	VIA SHIP'S CRANE & SHORE GRAB
Terminal courtsey/co-operation	ALL GOOD
Safety standard	ALL GOOD
Other information (booster pumps etc)	NIL

Additional information	
Authorities(Custom/immig./health)	ALL GOOD
Security (Stowaways/theft threats)	ALL GOOD
Spares/Stores/FW supply	ALL GOOD
Crew change/Shore leave	NIL / ALL GOOD
General comments	ALL GOOD
Recommendations	

Master's Name / Date	CAPT. DENIS R. DIEGO