

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback

Master's Name / Date

Port Feedback	
Ship Name	IVS RAFFLES
Port	BANG SAPHAN, THAILAND
Terminal & Berth No.	BERTH A2
Port Details	
Anchorage approach	BERTH IS NEAR ANCHORAGE
Min. depth at anchorage/Channel	
Pilot performance/Tugs condition	GOOD COOPERATION
Other information	
Berth Details	
Berth Type	GENERAL PURPOSE
Minimum depth at Berth/approach/UKC concern	
Mooring arrangement	4+2
Berth Restrictions	NO RESTRICTIONS
Berth condition/fendering etc	GOOD RUBBER FENDERS
Other information (fendering etc)	
Cargo Operation	
Manifold connections	NIL
Terminal courtsey/co-operation	GOOD
Safety standard	HIGH
Other information (booster pumps etc)	
Additional information	
Authorities(Custom/immig./health)	NORMAL PORT FORMALITIES
Security (Stowaways/theft threats)	NO SECURITY, STEVEDORES ARE THIEVES
Spares/Stores/FW supply	POSSIBLE
Crew change/Shore leave	NOT POSSIBLE/ SL IS ALLOWED
General comments	
Recommendations	