



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	BANG SAPHAN
Terminal & Berth No.	BERTH C2

Port Details

Anchorage approach	NE OF ENTRANCE LIGHT BUOY
Min. depth at anchorage/Channel	24/12m
Pilot performance/Tugs condition	SATISFACTORY / GOOD
Other information	

Berth Details

Berth Type	CONCRETE/FENDERED
Minimum depth at Berth/approach/UKC concern	11.7m / 12m / NIL
Mooring arrangement	4+2 FWD & AFT
Berth Restrictions	NONE
Berth condition/fendering etc	GOOD
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	GOOD / SATISFACTORY
Safety standard	SATISFACTORY
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	CUSTOM / IMMIGRATION / HEALTH CLEARED
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES / YES
General comments	VESSEL WILL DISCHARGE STEEL SLABS - 24584.25MT (4 GANGS). OPERATION TIME WILL BE 90 HRS.
Recommendations	

Master's Name / Date