



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS WENTWORTH
Port	KO SI CHANG, THAILAND
Terminal & Berth No.	WORKING ANCHORAGE 3

**Port Details**

Anchorage approach	The anchorage area is located within Lat. 13° 07' 00" N to Lat. 13° 08' 54" N, and Long. 100° 50' 00" E to Long. 100° 51' 00" E, The depth is approximately 20 m., the bottom is good holding ground,
Min. depth at anchorage/Channel	minimum depth of dredged channel 15.0m
Pilot performance/Tugs condition	1 pilot to drop anchor, no tugs to assist
Other information	discharging at anchorage

**Berth Details**

Berth Type	n/a
Minimum depth at Berth/approach/UKC concern	20.0m
Mooring arrangement	n/a
Berth Restrictions	n/a
Berth condition/fendering etc	n/a
Other information (fendering etc)	n/a

**Cargo Operation**

Manifold connections	NIL
Terminal courtesy/co-operation	Satisfactory
Safety standard	Satisfactory
Other information (booster pumps etc)	NIL

**Additional information**

Authorities(Custom/immig./health)	Satisfactory
Security (Stowaways/theft threats)	ISPS Port Compliant.
Spares/Stores/FW supply	No stores and FW received.
Crew change/Shore leave	Shore leave permitted,
General comments	
Recommendations	
Master's Name / Date	Pomorski Piotr P.