



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS HIRONO
Port	KOH SICHANG, THAILAND
Terminal & Berth No.	KOH SICHANG, ANCHORAGE

Port Details

Anchorage approach	KOH SICHANG ANCHORAGE
Min. depth at anchorage/Channel	18 M
Pilot performance/Tugs condition	WELL FAMILIAR OF ANCHORAGE AREA
Other information	CROWDED MIN DIST FROM OTHER SHIP 0.4 NM

Berth Details

Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	18 M / 3 M AT ANCHORAGE
Mooring arrangement	N/A
Berth Restrictions	COVID19 RESTRICTION, NO SHORE LEAVE
Berth condition/fendering etc	N/A
Other information (fendering etc)	N/A

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	ACCEPTABLE
Other information (booster pumps etc)	

Additional information

Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	NEED SPECIAL ATTENTION
Spares/Stores/FW supply	FW SUPPLIED FOR CARGO HOLD CLEAND
Crew change/Shore leave	NO CREW CHANGE AND NO SHORE LEAVE
General comments	LARGE NUMBER OF STEVEDORES FOR LOADING BAGS RICE
Recommendations	

Master's Name / Date	CAPT. A. BATA/14 AUG 2020
----------------------	---------------------------