

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS MERLION
Port	FUJAIRAH, UAE
Terminal & Berth No.	ANCHORAGE BRAVO

Port Details	
Anchorage approach	Outer anchorage as instructed by harbour master.
Min. depth at anchorage/Channel	Depth 89 mtrs
Pilot performance/Tugs condition	No pilot required when anchoring.
Other information	Anchorage B ( Vessel required Bunkering, and Stores)

Berth Details	
Berth Type	Outer Anchorage
Minimum depth at Berth/approach/UKC concern	Depth 89 mtrs
Mooring arrangement	Bunker barge lines for STS operation.
Berth Restrictions	Avoid passing anchorage area N and G.
Berth condition/fendering etc	Rubber type fenders
Other information (fendering etc)	N/A

Cargo Operation	
Manifold connections	Bunker Hoses,
Terminal courtsey/co-operation	Bunker personnel coopearte well
Safety standard	Complete PPE to be wear on deck.
Other information (booster pumps etc)	NIL

Additional information		
Authorities(Custom/immig./health)	NIL	
Security (Stowaways/theft threats)	NIL	
Spares/Stores/FW supply	YES	
Crew change/Shore leave	YES	
General comments		
Recommendations		•

Master's Name / Date	CAPT. RICHARD P. GEDALANGA / 26 JAN 2019