



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS HIRONO
Port	KHOR FAKKAN, UAE
Terminal & Berth No.	BERTH NO.6

Port Details

Anchorage approach	N/A
Min. depth at anchorage/Channel	16M
Pilot performance/Tugs condition	Pilot is very professional / Tugs good condition
Other information	

Berth Details

Berth Type	CONCRETE WITH BIG FENDERS
Minimum depth at Berth/approach/UKC concern	16M
Mooring arrangement	FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines
Berth Restrictions	NIL
Berth condition/fendering etc	well maintained berth / good fender
Other information (fendering etc)	PORT SIDE ALONG SIDE

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	GOOD POLICE PATROL ROUNDS EVERY HOUR
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	NIL
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	MAIN ENGINE LINER, PISTON RING, SKIRT. G/S PUMP SPARE PARTS RECEIVED, 135m3 OF FW RECEIVED
Crew change/Shore leave	SHORE LEAVE IS PROHIBITED / 3 CREW SIGN ON/FF
General comments	PORT SIDE ALONG SIDE
Recommendations	

Master's Name / Date	CAPT. RIZALDY MORELOS / MAR. 2020
----------------------	-----------------------------------