



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS RAFFLES
Port	ODESSA, UKRAINE
Terminal & Berth No.	KHLIBNA HARBOUR / BERTH # 43

Port Details

Anchorage approach	NO
Min. depth at anchorage/Channel	15.6
Pilot performance/Tugs condition	GOOD
Other information	NIL

Berth Details

Berth Type	DRY CARGO
Minimum depth at Berth/approach/UKC concern	13.2 meters
Mooring arrangement	4+2 (FWD & AFT)
Berth Restrictions	NIL
Berth condition/fendering etc	GOOD
Other information (fendering etc)	NIL

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	LOADING
Safety standard	STANDARD
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	SEC. LEV. 2
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL
General comments	NIL
Recommendations	

Master's Name / Date

CAPT. RICHARD P. GEDALANGA