

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS THANDA
Port	GIBRALTAR
Terminal & Berth No.	WEST ANCHORAGE

Port Details	
Anchorage approach	NO
Min. depth at anchorage/Channel	15
Pilot performance/Tugs condition	Pilot in good performance
Other information	

Berth Details	
Berth Type	ANCHORAGE WEST
Minimum depth at Berth/approach/UKC concern	15
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	N/A
Safety standard	N/A
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	BUNKERING STAFF ONLY
Security (Stowaways/theft threats)	No stowaway threats in this port
Spares/Stores/FW supply	NO
Crew change/Shore leave	NO
General comments	
Recommendations	

Master's Name / Date	Capt KRZYSZTOF M. MUCZYNSKI