

Master's Name / Date

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B

Date: 02/June/2017

Rev: 1.0 App By: BMM

Port Feedback	
Ship Name	IVS MERLION
Port	LONGBEACH CALIFORNIA, USA
Terminal & Berth No.	LB - 211 / KOCH (KCBX), LONGBEACH CALIFORNIA, USA
Port Details	
Anchorage approach	ANCHOR TO INNER ANCHORAGE ENTERING BRKWATER
Min. depth at anchorage/Channel	14.0 MTR
Pilot performance/Tugs condition	GOOD
Other information	
Berth Details	
Berth Type	BULK TYPE TERMINAL
Minimum depth at Berth/approach/UKC concern	14.0 MTR BERTH DEPTH
Mooring arrangement	PORT SIDE ALONGSIDE 4-2-2 (FORWARD & AFT)
Berth Restrictions	DRAFT RESTRICTION; APPROX 39 FT 7 INCHES
Berth condition/fendering etc	GOOD
Other information (fendering etc)	NIL
Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD
Safety standard .	GOOD
Other information (booster pumps etc)	N/A
Additional information	
Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	YES / NO STOWAWAYS & NO THREATS
Spares/Stores/FW supply	YES
Crew change/Shore leave	YES
General comments	
Recommendations	

DARIUSZ WIEWIORKOWSKI / 26 JAN. 2018

50