



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS SPARROWHAWK
Port	CORPUS CRISTI USA
Terminal & Berth No.	DOCK 09

Port Details

Anchorage approach	Approach is from the ESE within a safety railway, through Aransas Pass and then by a 13.7m dredged channel. Entry is from the W end. The limits of outer railway anchorages are crated with the following mid positions:
Min. depth at anchorage/Channel	
Pilot performance/Tugs condition	Pilot is good and tugs are adequate
Other information	The main port area of Corpus Christi is located on the w coast of the Gulf of Mexico, approx 18nm from open sea, in Corpus Christi Bay.

Berth Details

Berth Type	Cargo terminal
Minimum depth at Berth/approach/UKC concern	10.97m
Mooring arrangement	4+2 fwd and aft
Berth Restrictions	No berth restrictions
Berth condition/fendering etc	Berth has adequate fenders. And discharging using ships crane
Other information (fendering etc)	

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good and approachable.
Safety standard	Safety standards are in place.
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	Professional and courteous.
Security (Stowaways/theft threats)	ISPS compliant port.
Spares/Stores/FW supply	Receive bunker
Crew change/Shore leave	Shore leave permitted only the crew that they have a U.S. visa
General comments	Good sheltered port.
Recommendations	

Master's Name / Date: 30 May 2018

Capt. Constancio M. Lavilla jr.